

HEAD OF SURVEILLANCE AND INSPECTION CENTER GREENHOUSE GAS VERIFICATION STATEMENT



Certificate Number

Report Number

Date of Verification Statement

Company Title Company Address SER.006.2024/B00040 SER.006.2024/R00016

14.06.2024

DYO BOYA FABRİKALARI SANAYİ VE TİCARET ANONİM ŞİRKETİ

AOSB MAH. 10003 SK. NO:2/8 ÇİĞLİ

Purpose of Verification

Verifying the Greenhouse Gas Statement dated 13.06.2024 of the company has been prepared according to TS EN ISO 14064-1:2019 standard for the period from 01.01.2022 to 31.12.2022and that the Greenhouse Gas Statement is free from material misstatements at "Reasonable Level of Assurance" according to the requirements of the TS EN ISO 14064-3:2019 standard.

Verification Methodology

Verification of the Greenhouse Gas Statement has been carried out in accordance with requirement of TS EN ISO 14064-3:2019 standard.

Techniques of Verification

Greenhouse gas information system controls and greenhouse gas data / information are evaluated by document review, site visits and recalculation methods and on the basis of the evidence of Greenhouse Gas Statement is verified.

Verification Criteria Verification Period Base Year

Organizational Boundaries

TS EN ISO 14064-1:2019 01.01.2022- 31.12.2022

2022

AOSB MAHALLESI 10003 SK. NO: 2/8 ÇIĞLI / İZMİR

Types of Greenhouse Gases

CO₂, CH₄, N₂O

Verified GHG Emissions and Removals

Category 1 Category 2 Category 3 Direct Emissions Energy Indirect Emissions Indirect Emissions due to

4.066,82 ton CO₂e 5.122,33 ton CO₂e 10.046,67 ton CO₂e

Category 4

Indirect Emissions from

Transportation

125.862,23 ton CO₂e

Category 5

Products/Services of the Organization Indirect Emissions related to use of

ton CO₂e

Products
Category 6 Other Inc

Other Indirect Emissions

ton CO₂e

Direct Emissions from Biomass

No emission from biomass

Not quantified by the

GHG Removals

company

Carbon Credits

Not *declared* by the *company*

Level of Assurance

Reasonable Assurance Level

Verification Opinion

Verified as Satisfactory with Comments

Mehmet ERGÜN

Director of Environmental/Surveillance and Verification



https://basvuru.tse.org.tr/uye/QRKodDogrulama?code=F63C4D You can query this address to check the accuracy and validity of the document.

^{*} Yüzüncü Yıl Bulvarı Cevat Dündar Caddesi 1236. Sokak No:1 Yenimahalle/ANKARA